

Issued to:
ACCURATE SAFETY & SECURITY 4 BLACKBURN ROAD ACCRINGTON LANCASHIRE
BB5 1HD

Location of equipment:
HEAVY HANDED LTD 4 AMYROYCE DRIVE BRADFORD
BD18 1LE

Issued by:
Lloyds British a division of Speedy Asset Services Ltd Brunel Industrial Estate Blyth Road Harworth DN11 8QA Tel: 01302 751267



Report no:	PRJ-022293/006
Your Order no:	VERBAL PAUL
Our Job no:	PRJ-022293
Sheet no:	1 of 1

Report of Test and Thorough Examination of Lifting Plant and Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998, SI 2307

Identification Mark of the Equipment:	Description of Equipment	Details of Test and Thorough Examination				
		Qty Tested and Examined:	Safe Working Load: (Specify Units)	Proof Load Applied: (Specify Units)	Additional/Examination/Standards	Date of Test and Examination:
BATCH TEST AS003	ACCURATE SAFETY MESH PANEL (AS003) OVERALL DIMENSIONS 2555MM X 1050MM SUPPORTED 2300MM CENTRES BY 2 NUMBER ACCURATE SAFETY POSTS 1.1MTR (AS005) FIXED INTO CONCRETE USING 2 X M12 X 75MM LIGHTNING BOLTS	1	N/A	67.5 KG STATIC LOAD	LOAD APPLIED AT 1MTR HIGH ON PANEL DEFLECTION = 55MM PASS RETURNED WITH NO PERMANENT SET STANDARD CANADIAN/ONTARIO REGULATION 213/91	16/01/19

The above equipment has been thoroughly examined, no defects found and is safe to operate



Name and address of person authenticating and signing this report on behalf of author:

Name: IAN WILMOT

Position: TEST ENGINEER

Signature:

Date of Report: 29TH JANUARY 2019



Issued to:
ACCURATE SAFETY & SECURITY 4 BLACKBURN ROAD ACCRINGTON LANCASHIRE
BB5 1HD

Location of equipment:
HEAVY HANDED LTD 4 AMYROYCE DRIVE BRADFORD
BD18 1LE

Issued by:
Lloyds British a division of Speedy Asset Services Ltd Brunel Industrial Estate Blyth Road Harworth DN11 8QA Tel: 01302 751267



Report no:	PRJ-022293/013
Your Order no:	VERBAL PAUL
Our Job no:	PRJ-022293
Sheet no:	1 of 1

Report of Test and Thorough Examination of Lifting Plant and Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998, SI 2307

Identification Mark of the Equipment:	Description of Equipment	Details of Test and Thorough Examination				
		Qty Tested and Examined:	Safe Working Load: (Specify Units)	Proof Load Applied: (Specify Units)	Additional/Examination/Standards	Date of Test and Examination:
BATCH TEST AS005	ACCURATE SAFETY POSTS 1.1MTR (AS005) FIXED INTO LAMINATED TIMBER USING 4 X M6 X 100MM HECOTOPIX SCREWS OVERALL DIMENSIONS 60MM X 40MM X 1135MM	1	N/A	67.5 KG STATIC LOAD	LOAD APPLIED AT 1MTR HIGH ON POST DEFLECTION = 30MM RETURNED WITH NO PERMANENT SET STANDARD CANADIAN/ONTARIO REGULATION 213/91	16/01/19

The above equipment has been thoroughly examined, no defects found and is safe to operate



Name and address of person authenticating and signing this report on behalf of author:

Name: IAN WILMOT

Position: TEST ENGINEER

Signature:

Date of Report: 29TH JANUARY 2019

