

| |
|--|
| Issued to: |
| ACCURATE SAFETY & SECURITY 4 BLACKBURN ROAD ACCRINGTON LANCASHIRE |
| BB5 1HD |

| |
|--|
| Location of equipment: |
| HEAVY HANDED LTD 4 AMYROYCE DRIVE BRADFORD |
| BD18 1LE |

| |
|--|
| Issued by: |
| Lloyds British a division of Speedy Asset Services Ltd Brunel Industrial Estate Blyth Road Harworth DN11 8QA Tel: 01302 751267 |



| | |
|-----------------------|----------------|
| Report no: | PRJ-022293/007 |
| Your Order no: | VERBAL PAUL |
| Our Job no: | PRJ-022293 |
| Sheet no: | 1 of 1 |

Report of Test and Thorough Examination of Lifting Plant and Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998, SI 2307

| Identification Mark of the Equipment: | Description of Equipment | Details of Test and Thorough Examination | | | | |
|---------------------------------------|--|--|------------------------------------|-------------------------------------|---|-------------------------------|
| | | Qty Tested and Examined: | Safe Working Load: (Specify Units) | Proof Load Applied: (Specify Units) | Additional/Examination/Standards | Date of Test and Examination: |
| BATCH TEST AS003 | ACCURATE SAFETY MESH PANEL (AS003) OVERALL DIMENSIONS 2555MM X 1050MM SUPPORTED 2300MM CENTRES BY 2 NUMBER ACCURATE SAFETY POSTS 1.1MTR (AS005) FIXED INTO CONCRETE USING 2 X M12 X 75MM LIGHTNING BOLTS | 1 | N/A | 91 KG STATIC LOAD | LOAD APPLIED AT 1MTR HIGH ON PANEL DEFLECTION = 76MM PASS DEFLECTION RECORDED = 70MM RETURNED WITH NO PERMANENT SET STANDARD AMERICAN STANDARD OSHA 1926-502 ANSI/ASSE A10.18-2007 | 16/01/19 |

The above equipment has been thoroughly examined, no defects found and is safe to operate



Name and address of person authenticating and signing this report on behalf of author:

Name: IAN WILMOT

Position: TEST ENGINEER

Signature: 

Date of Report: 29TH JANUARY 2019



| |
|--|
| Issued to: |
| ACCURATE SAFETY & SECURITY 4 BLACKBURN ROAD ACCRINGTON LANCASHIRE |
| BB5 1HD |

| |
|--|
| Location of equipment: |
| HEAVY HANDED LTD 4 AMYROYCE DRIVE BRADFORD |
| BD18 1LE |

| |
|--|
| Issued by: |
| Lloyds British a division of Speedy Asset Services Ltd Brunel Industrial Estate Blyth Road Harworth DN11 8QA Tel: 01302 751267 |



| | |
|-----------------------|----------------|
| Report no: | PRJ-022293/014 |
| Your Order no: | VERBAL PAUL |
| Our Job no: | PRJ-022293 |
| Sheet no: | 1 of 1 |

Report of Test and Thorough Examination of Lifting Plant and Equipment

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998, SI 2307

| Identification Mark of the Equipment: | Description of Equipment | Details of Test and Thorough Examination | | | | |
|---------------------------------------|---|--|------------------------------------|-------------------------------------|--|-------------------------------|
| | | Qty Tested and Examined: | Safe Working Load: (Specify Units) | Proof Load Applied: (Specify Units) | Additional/Examination/Standards | Date of Test and Examination: |
| BATCH TEST AS005 | ACCURATE SAFETY POSTS 1.1MTR (AS005) FIXED INTO LAMINATED TIMBER USING 4 X M6 X 100MM HECOTOPIX SCREWS OVERALL DIMENSIONS 60MM X 40MM X 1135MM | 1 | N/A | 91 KG STATIC LOAD | LOAD APPLIED AT 1MTR HIGH ON POST DEFLECTION = 63MM RECORDED = 76MM PASS RETURNED WITH NO PERMANENT SET STANDARD AMERICAN OSHA 1926-502 ANSI/ASSE A10.18-2007 | 16/01/19 |

The above equipment has been thoroughly examined, no defects found and is safe to operate



Name and address of person authenticating and signing this report on behalf of author:

Name: IAN WILMOT

Position: TEST ENGINEER

Signature:

Date of Report: 29TH JANUARY 2019

